Endobronchial coil penetration into the pleural space

Giampietro Marchetti,¹ David J McCracken,² Najib M Rahman^{2,3}

► Additional material is published online only. To view please visit the journal online (<http://dx.doi.org/10.1136/thoraxjnl-2018-211754>).

¹Divisione di Pneumologia, Spedali Civili di Brescia, Brescia, Italy

²Oxford Centre for Respiratory Medicine, Oxford University Hospitals, Oxford, UK

³Oxford Respiratory Trials Unit, Oxford University Hospitals, Oxford, UK

Correspondence to

Dr David J McCracken, Oxford Centre for Respiratory Medicine, Oxford University Hospitals, Oxford OX3 7LE, UK; dmccracken04@qub.ac.uk

Received 28 February 2018

Accepted 5 March 2018

Published Online First

24 March 2018

CASE

A patient with severe emphysema, post pulmonary rehabilitation and on full inhaled treatment underwent elective placement of eight endobronchial coils (RePneu Lung Volume Reduction Coils) in the right lung to attempt endoscopic lung volume reduction, targeted at the upper and lower lobes. The patient was not suitable for surgical open lung volume reduction and was unable to undergo valve treatment due to homogenous disease and an incomplete fissure on thoracic CT. Twelve hours post endobronchial treatment, the patient experienced chest pain and respiratory distress, and a large right pneumothorax was demonstrated on chest radiograph. The patient required immediate chest tube insertion, and chest radiographs pre chest tube insertion and post chest tube insertion demonstrated a coil visible in the right costophrenic angle adjacent to the collapsed lung (figure 1A,B),

which had entirely migrated into the pleural space. Thoracic CT confirmed the pleural coil position (figure 2A). As thoracic surgery was not feasible due to anaesthetic risk, medical thoracoscopy was undertaken under local anaesthetic and sedation. The coil was identified in the pleural space (figure 2B) and successfully removed (online supplementary video 1). The pneumothorax resolved over 48 hours of chest tube drainage post thoracoscopy, and the patient was discharged.

Although pneumothorax is a known complication of coil insertion, occurring in 9.7% of cases,¹ the usual mechanism is thought to be expansion of the non-treated lobe resulting in visceral tear and leak. Coil migration to cause visceral tear² and incomplete migration have been reported,³ but to our knowledge, this is the first report identifying complete migration into the pleural space and coil rescue via medical thoracoscopy.

Figure 1 (A) Post procedure large pneumothorax with the coil visible (arrow) in the pleural space. (B) The coil in situ (arrow) post lung expansion after chest tube insertion.

Figure 2 (A) The coil (arrow) visible in the pleural space within pneumothorax. (B) The thoracoscopic view (D, diaphragm, L, lung, P, parietal pleural surface) with the coil in the pleural space (arrow) with a small haemothorax.

To cite: Marchetti G, McCracken DJ, Rahman NM. *Thorax* 2018;**73**:890–891.

Funding The authors have not declared a specific grant for this research from any funding agency in the public, commercial or not-for-profit sectors.

Competing interests None declared.

Patient consent Obtained.

Provenance and peer review Not commissioned; externally peer reviewed.

© Article author(s) (or their employer(s) unless otherwise stated in the text of the article) 2018. All rights reserved. No commercial use is permitted unless otherwise expressly granted.

REFERENCES

- 1 Sciurba FC, Criner GJ, Strange C, *et al.* Effect of endobronchial coils vs usual care on exercise tolerance in patients with severe emphysema: the renew randomized clinical trial. *JAMA* 2016;315:2178–89.
- 2 Mongelli F, Cafarotti S, Di Giuseppe M, *et al.* Late onset of pneumothorax after bronchoscopic lung volume reduction due to migration of a nitinol coil. *Eur J Cardiothorac Surg* 2017.
- 3 Metin B, Yildirim S. Removal of the coil applied by bronchoscopy for emphysema treatment by means of thoracoscopy. *J Ann Eu Med* 2016;4(Suppl 1):10–12.